

# Release notes for HTR02 Main firmware

---

Copyright © 2023 SENSEOR

## **v4.0.3**

- Fix database memory issue.
- Fix ambient sensor data issue.
- SAW installation improvement.

## **v4.0.2**

- Fix memory corruption issue.
- SAW measurement algorithm improvement.
- SAW installation method improvement.
- Update Modbus table to v1.2.0.

## **v3.3.2**

- Fix PDD firmware update issue.
- "Analog In" feature no longer supported.