

Release notes for AMS01 firmware

Copyright © 2023 SENSEOR

v1.3.6.0

- Add Partial Discharge measurement feature.
- Add environmental sensor measurement.
- SAW measurement improvement.
- SAW installation improvement.
- Fix Modbus issue.

v1.2.8.0

- First release with temperature measurement only.

Compatibility information

In this table, you can find the successive versions of AMS01 firmware in line with the AMS01 Configuration Tool.

AMS01 firmware	AMS01 Configuration Tool
v1.3.6.0	v1.1.3
v1.2.8.0	v1.0.4