

Release notes for AMS01 firmware

Copyright © 2024 SENSEOR

v1.6.0.0

- Faster commissioning of temperature sensors thanks to improved algorithm.
- Temperature sensors measurement improvement.

v1.5.6.0

- Fix faulty SD card detection issue.

v1.5.5.0

- Fix Modbus-TCP issue.

v1.5.4.0

- Add "System Test" feature (instantaneous sensors and partial discharge test measurement mode).
- Add "Notifiers" feature (alarm mechanism on measurement data for sensors and partial discharge probes).
- New AMS01 Modbus table v1.1.0 (includes Notifier registers).
- Fix Ethernet communication issue.
- Fix instantaneous refresh of environmental sensor issue.

v1.4.3.0

- Add compatibility mode with HTR02 reader feature (Modbus table v1.2.0).
- Temperature sensors measurement improvement.
- Fix Fahrenheit temperature conversion issue.

v1.3.7.0

- Compatible with AMS01 product types AMS01-T, AMS01-P & AMS01-TP.

v1.3.6.0

- Add Partial Discharge measurement feature.
- Add environmental sensor measurement.
- Temperature sensors measurement improvement.
- Temperature sensors installation improvement.
- Fix Modbus issue.

v1.2.8.0

- First release with temperature measurement only.

Compatibility information

In this table, you can find the successive versions of AMS01 firmware in line with the AMS01 Configuration Tool.

AMS01 firmware	AMS01 Configuration Tool
v1.6.0.0	v1.5.1
v1.5.5.0	v1.4.3
v1.4.3.0	v1.2.6
v1.3.7.0	N/A
v1.3.6.0	v1.1.3
v1.2.8.0	v1.0.4